


SPRU BUSH



SPRU BUSH (NON HARDEN)

D g6	L2	L1	L	H	(a - b)
13.5, 16.5, 20.5, 27.0	25	25	50	30	(3.3 - 3.5) - 6.5 - 7.0
	32		57		
	40	25	65	20	(3.4 - 3.7) - (7.0 - 8.0)
	50		75		
	65		90		
	75		100		
	90		115		
	100		125		
	125		150		
	150		175		
	175	200	30	(3.8 - 4.5) - (8.0 - 10.0)	
	200	225			
	225	250			
		250	275		

SPRU BUSH (HARDEN)

D g6	L2	L1	L	H	(a - b)
12.0, 16.0, 20.0	25		50	30	3.5 - 7.0
	32		57		
	40		65		
	50	25	75	30	3.5 - 8.0
	65		90		
	75		100		
	90		115		
	100		125		
	125		150		
	150		175		